

Microsoft Exchange Server 2007 Unified Messaging PBX Configuration Note

This document is for informational purposes only. Microsoft and its partners and vendors cannot verify the accuracy of this information and take no responsibility for the content of this document. MICROSOFT AND ITS PARTNERS AND VENDORS MAKE NO WARRANTIES, EXPRESS OR IMPLIED, IN THIS DOCUMENT.

Filename : Mitel-3300-SIP/Minet-Direct SIP connection_preview.doc

Date modified : 2007-02-06

1. PBX OR IP-PBX ADDRESSED

PBX Vendor	Mitel
Model	3300 CXi, CX / MXe
Software Version	7.1 UR2
Additional Notes	Direct SIP connection from Mitel to Exchange 2007

2. UM GATEWAY

Gateway Vendor	NA
Model	NA
Software Version	NA
Protocol	Protocol - NA

3. AUTHOR(S)

Company	Mitel
Last Modified By	SIP Interop (sipinterop@mitel.com)
Last Modified Date	2007-02-21
Modification Details	If updating the document, describe the modification details here. Otherwise, write N/A.

Version History

Modified By	Name (Email)
--------------------	--------------

Modified Date	yyyy-mm-dd
Modification Details	

4. PREREQUISITES

4.1. GATEWAY PREREQUISITES

- *The 3300 ICP should be running Release 7.1UR2 or later software.*
- *SIP trunking licenses must be acquired.*
- *If 3300 ICP is deployed as a Gateway between a legacy PBX and Exchange Server 2007 it must be equipped with a Digital Trunk interface module (e.g. dual framer T1/E1 MMC) and related licences must be acquired*

4.2. PBX PREREQUISITES

- *The 3300 ICP should be running Release 7.1UR2 or later software.*
- *SIP trunking licences must be acquired.*

4.2.1. PBX EQUIPMENT REQUIRED

List any specialized PBX hardware required.

- *None.*

4.3. CABLING REQUIREMENTS

- *Standard IP/Ethernet connection*

5. OPERATION SUMMARY AND LIMITATIONS

A check in this box indicates the UM feature set is fully functional when using the PBX/gateway in question.

The following limitations are related to the integration of 3300 ICP with the UM Server:

- *TLS is not supported by the 3300 ICP R7.1 UR2*
- *T.38 fax is not directly supported by the 3300 ICP*
- *Play-On-Phone feature is supported only for IP Phones connected to the 3300 ICP*